



BP Australia Pty Ltd
ABN 99 008 422 115

BP Refinery (Bulwer Island) Pty Ltd
398 Tingira Street
Pinkenba QLD 4053

Postal Address:
PO Box 4 Pinkenba QLD 4008

Dear Michael,

Thank you for Building Solutions Brisbane's efforts and workmanship in the six years we have worked together at BP Refinery, Bulwer Island.

I would happily recommend your company for any fireproofing and concrete repairs. It was great to have some extra competition onsite who could keep low overheads and still have strong supervision.

Your staff always conducted themselves professionally, and were obliging to work in adverse weather conditions. I would happily recommend your company to others. Feel free to share this letter with others when tendering for work.

To anybody reading this I would happily recommend and endorse Building Solutions Brisbane. They have worked onsite at the BP Refinery for over six years, with no safety issues. Tasks they undertook included structural remediation, concrete repairs, and fireproofing (removal and installation). Building Solutions Brisbane also conducted a fireproofing survey and assessment which allowed us to intervene and prevent further corrosion under fireproofing/insulation.

Kind Regards,

Tim Kehoe

Project/Maintenance Engineer

BP Refinery (Bulwer Island)

Phone: + 61 7 3243 7520

timothy.kehoe@bp.com